CONDEMNED

vogen plune contact

221-3310 (panted on her)

SALVAGE.

## DAMAGE ASSESSMENT FORM

Building Name					
Address 16401 Sw 248					
City (or Vicinity) and Count	ty Miami	Fi (Re	EDLANDS)		
Owner					
Date of Construction Folio No					
Primary Use					
M Residential (1-2 units) [] Commercial [] Industrial/Warehouse	[] Residential [] Mixed [] Hotel/Motel	3+ units) [ [ [	] Office Buildir ] Church ] Bank	ng [] School [] Lodge [] Other	
Description					
[] Freestanding [] Basement [] Electrical System	[] Row [] Attic		No. of Stories / No. Chimney(s) /		
Construction Type					
[] Masonry Bearing Wall [] Veneer/Concrete Frame	[] Veneer/Steel [] Concrete Unit	Frame (X	Wood Frame   Other <u>ADDITIO</u>	[] Concrete N-FRAME/stucco	
Surface Covering		- 1	in "This seed " used	en den e din	
Stucco new addition (west) [ Wood Siding (lap/other) [] Stone [] Other [N Roof ASPHINT OVER WOOD SIAT					
Foundation					
[] Concrete Slab [] Block	[] Limestone Rul	oble [] Oth	er	[] Unknown	
Geological Natural of Site					
Bedrock [] Soil/Sand [] Fill [] Other [] Unknown					
Historical Designation					
[] National Register [] [] Dade County Historic Surv				Jnknown	
Failing Hazards Haz	zards No Appa	arent Hazard	Unknown (	Comments	
Chimney(s) [ Floors [ Roof Structure [ Equipment [ Trees [			[]	Consensed/ Lectra/aut	

Failing Hazards (Con't)		•		
	Hazards	No Apparent Haza	ard Unknown	Comments
Parapet/Cornice	[]	M	[ בֿ בַ	
Ornamentation Other	[]		[] []	
Fire Hazards		75		
[] Electrical		Debris	[] Gas _	
Damage Observations	None Sligh	ng Scale (0%) 0 nt (1—10%) 1 rate (11—40%) 2—3—4	Severe (4 Total (ov Not Obser Not Appli	er 60%) 6 ved: NO
SEE COMMENTS		Z	Comments	
Exterior Walls				
Frame (General Condition)				
Frame Members				
Frame Connections			•	
Roof Framing				
Roof Covering				
Foundation				
Chimney(s)			-	
Doors				
Windows and Shutters				
Porch				
Downspouts and Gutters				
Interior Bearing/Shear Wal	ls			
Partitions (Nonbearing)				
Floor(s)				
Stair(s)		-	·j.	
Glass			-	, *
Mechanical Equipment		?		ă
Electrical Equipment			Hook ys - prince	ing down
Garden and Trees		6		
Fences and Garden Walls		6	noncombib fen	u
Walkways and Sidewalks				
Other:				
Total Damage				

Overall Structural Assessment
[] No Damage or Easily Repairable [] Damage Repairable Damage Will Require Massive Repair/Reconstruction
Recommendations for Further Inspection <u>Elicthic</u> Smuchunal
Recommendations for Immediate Actions STABIL North ATTIC WALL - PRACING T
ENTIRE NORTH WALL OF ORICINAL STRUCTURE; BRACE AT SW
CORNER OF DRIGHAL SANUETURE
Recommendations for Future Repair Work Tutme nestonation - Lemone inappropriate waternals; west wing ADDITION
Recommendations for Immediate Stabilization See Action, Northware @ ATTLE bowed & leaning slightly worthward - Bracing At North ware!
Salvageable Materials
Wood siding (lap, other) Structural members (Dade County Pine) loop & Fram
[] Fixtures/hardware [] Other look slats
Interior hat newed -no photos
PORCH CETLING - RECESSED CENTER & SEAM BEAD - 1X4-

## Landscape Assessment

Site Sketch:

(Significant landscape features, large old trees, (standing/down) walls, paths, groves (type)).

N/A

Comments: NORTH WALL BOWED OUT - PUSSIBLE TO "SNAP" BACK IF BOLLOON

Inspector(s) S. Lewis Agency/Team DOTT Date 11-3-92
Photographs or Video (Roll and Numbers) SEE METRO / DADE (T. Lenox 11-2-92)